

Mannix, John <mannixj@monroe.wednet.edu>

Sky Valley Post Abatement Sample Review

1 message

Gregg Middaugh < Gregg.Middaugh@pbsenv.com>

Fri, Sep 9, 2016 at 11:27 AM

To: John Mannix <mannixj@monroe.wednet.edu>, "Piplic, Devlin" <piplicd@monroe.wednet.edu>

Cc: Celerino Alvarez < Cel. Alvarez @pbsenv.com>

The following summarizes the lab results for the post abatement wipe samples collected at Sky Valley.

There were detectable concentrations of PCBs found on a total of 9 samples as follows:

#2040 CTE Classroom Concrete Floor Under Window- 1.3 ug/100cm²

#2057 Administration NW Corner Ext. Concrete Sidewalk – 1.3 ug/100cm²

#2060 Administration SE Corner Ext. Concrete Sidewalk – *12 ug/100cm²

#2069 Room 7 Ext. Concrete Sidewalk – 5.4 ug/100cm²

#2078 Room 16 Ext. Concrete Sidewalk – 8 ug/100cm²

#2085 Gyms Commons (Gathering Place) West Ext. Concrete Sidewalk- 7.2 ug/100cm²

#2087 Gym NW Ext. Concrete Sidewalk – 1.9 ug/100cm²

#2088 Small Gym Wood Floor - *13 ug/100cm²

#2091 Girls Locker Room (Gym North) Exterior Asphalt Under Window – 2.8 ug/100cm²

All areas with detectable concentrations of PCBs have been recleaned.

*Two samples (bolded) were above EPA Criteria of 10ug/100cm² PCBs. Resampling of the two areas above the criteria revealed the following:

#2094 Administration SE Corner Ext. Concrete Sidewalk - Non-detect

#2095 Small Gym Wood Floor - Non-detect

(see attached lab results)

Gregg Middaugh | Senior Project Manager - Industrial Hygiene

Gregg.Middaugh@pbsenv.com

direct: 206.766.7613 : cell: 206.255.4659

PBS Engineering and Environmental

Engineering | Industrial Hygiene | Environmental | Planning | Surveying www.pbsenv.com 2517 Eastlake Ave. East, Seattle, WA 98102 office: 206.233.9639 : fax: 866.727.0140

This electronic communication and its attachments are intended only for the person(s) to whom it is addressed and may contain confidential information. If you are not the intended recipient of this message, you are hereby notified that any use, retransmission, distribution, reproduction or any action relying upon this message is prohibited. If you have received this information in error, please notify the sender.

